MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT
14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

INACTIVE

D005000

Inactive type Permit has no description information.

EXPIRES LAST DAY OF: NOVEMBER 1998

OWNER OF OPERATOR (Co.#87)

Commanding Officer, MCLB Barstow, CA
Box 110570 Bldg 196 Attn: Air Program Manager
Barstow, CA 92311-5050

EQUIPMENT LOCATION (Fac.#587)

USMC MCLB - Yermo Annex
USMC Logistics Base
Barstow, CA 923115013

Description:
DEGREASER, DIP TANK, P-9 at Warehouse 5, near N Iwo Jima & A Streets consisting of: a Kleer-Flo, Model No. Powermaster 500, Serial No. 500-1645, whose surface area is 15.7 ft2 (55" x 41") and whose Volume of Solvent is 200 gallons. The solvent is a light lubricating oil. This unit includes a Cover for Top and operates at ambient temperatures.

CONDITIONS:

1. The tank shall be equipped with a tight fitting cover.

2. The tank cover shall be closed at all times when the tank is not in use.

3. The tank shall have a Freeboard Height of at least 5 inches while the items are submerged. The Freeboard Height is the distance from the top of the liquid to the top of the tank.

4. Parts shall be added to or removed from the tank in a manner which prevents splashing.

5. Before parts are removed from the tank they shall appear visually dry.

Fee Schedule: 7 (d)	Rating: 1 device	SIC: 9711	SCC: 99999999	Location/UTM(Km): 512E/3861N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

Commanding Officer, MCLB Barstow, CA
Box 110570 Attn: Air Program Manager
Barstow, CA 92311-5050

By: **COPY**
Brad Poiriez
Executive Director

UNOFFICIAL

6. The hoist speed shall be slow enough to prevent solvent vapors from being pushed and/or pulled out of the tank. Furthermore, the hoist speed shall not exceed 11.2 feet per minute.

7. A log shall be maintained which contains, as a minimum, the type of solvent in each tank, date and amount of solvent added, and a daily self-inspection checklist. The log shall be maintained current, on-site for a minimum of 2 years and provided to the District upon request.

8. This dip tank shall be operated and maintained in strict accord with manufacturer's/supplier's recommendations and/or sound engineering principles which produce the minimum emissions of the solvent.