

MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park AvenueVictorville,CA92392-2310 760.245.1661 -- 800.635.4617 -- FAX760.245.2022

RENEWAL

т013324

Renewal type Permit has no description information.

EXPIRES LAST DAY OF: JUNE 2025

OWNER OF OPERATOR (Co.#2500)

5E Boron Americas, LLC 9329 Mariposa Rd. Suite # 210 Hesperia,CA92344

EQUIPMENT LOCATION (Fac. #3893)

5E Boron Americas, LLC 27555 Hector Road Newberry Springs,CA92365

Description:

STORAGE TANK, HYDROCHLORIC ACID consisting of:A 17,500 gallon storage tank for aqueous Hydrochloric Acid (HCI) with an approximate concentration of 31.7% HCI w/w. The tank receives HCI from the HCI Absorbers and Gypsum precipitators and delivers it to the HCI Injection system. The annual throughput is approximately 8.8 MMGal of HCI. The tank is completely enclosed to minimize emissions.

CONDITIONS:

1. This equipment shall be installed, operated and maintained in strict accordance with those recommendations of the manufacturer/supplier and/or sound engineering principles which produce the minimum emissions of contaminants. Unless otherwise noted, this equipment shall also be operated in accordance with all data and specifications submitted with the application for this permit. [District Rules 204 and 1303]

2. The owner/operator shall inspect the system for aqueous HCl leaks weekly. A leak shall be defined as more than one drop per minute of liquid capable of turning a wetted piece of pH test paper to a color indicating a pH of 1 or less. All leak inspections shall be recorded and all leaks shall be repaired within one week of discovery. [District Rules 1302 and 1320]

3. The owner/operator shall maintain a current, on-site (at a central location if necessary) operations log for this equipment for five (5) years, which shall be provided to District, State or Federal personnel upon request. This log shall include, as a minimum, the results of all tests, inspections (including the weekly HCI leak inspections discussed in Condition #2), repairs, and maintenance actions, as occurring. [District Rule 1302]

Fee Schedule:5 (b)

Rating:17500gallons SIC:1479

S

SCC:30101198

Location/UTM(Km):552E/3846N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

5E Boron Americas, LLC 9329 Mariposa Rd. Suite # 210 Hesperia,CA92344



Brad Poiriez Air Pollution Control Officer

- 4.Emissions from the entire facility shall not exceed the following limits:
- a. Oxides of Nitrogen (NOx): 24 tons per consecutive twelve month period, measured as NO2;
- b. Oxides of Sulfur (SOx): 24 tons per consecutive twelve month period;
- c. Volatile Organic Compounds (VOC): 24 tons per consecutive twelve month period;
- d. Carbon Monoxide (CO): 95 tons per consecutive twelve month period;
- e. Hydrogen Sulfide (H2S): 9.5 tons per consecutive twelve month period;
- f. Lead (Pb): 0.5 tons per consecutive twelve month period;
- g. Particulate Matter 10 microns and less (PM10): 14.5 tons per consecutive twelve month period;
- h. Any single Hazardous Air Pollutant (HAP): 9.5 tons per consecutive twelve month period; and
- i. All HAPs combined: 24 tons per consecutive twelve month period.

Compliance shall be demonstrated to the District through the submission of a District approved Comprehensive Emission Inventory Report (CEI) or other equivalent and District approved method. [District Rules 1302 and 1320]

5.A facility wide Comprehensive Emission Inventory (CEI) for all emitted criteria and toxic air pollutants must be submitted to the District, in a format approved by the District, upon District request. [District Rule 107(b), H&S Code 39607 & 44341-44342, and 40 CFR 51, Subpart A]