



**MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT**

14306 Park Avenue Victorville, CA 92392-2310  
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

**INACTIVE**

G000572

Inactive type Permit has no description information.

**EXPIRES LAST DAY OF: SEPTEMBER 2010**

**OWNER OF OPERATOR (Co.#106)**

BP West Coast Products LLC  
4 Centerpointe Dr.  
La Palma, CA 90623-1066

**EQUIPMENT LOCATION (Fac.#94)**

ARCO #5215 /Prestige Station #715  
57858 29 Palms Highway  
Yucca Valley, CA 92284

**Description:**

GASOLINE DISPENSING FACILITY consisting of:

**FUEL TANKS**

Tank No.	Material Stored	Volume (US Gallons)	Above/Underground
1	87U	10,000	Under Ground
2	87U	10,000	Under Ground
3	89U	10,000	Under Ground
4	91U	10,000	Under Ground

**DISPENSING EQUIPMENT**

Fuel Type	Quantity
TPN	24

**VAPOR CONTROL EQUIPMENT**

Type	Equipment Name	Compliance
PI	DP	VR-102-D
PII	HEALY	VR-202-E

Fee Schedule: 6 (N/A)

Rating: 24 product-nozzles SIC: 5541

SCC: 40600603

Location/UTM(Km):  
551E/3776N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

BP West Coast Products LLC  
Attn: Becky Stackhouse  
  
Artesia, CA 90702-6038

By: **COPY**  
**Eldon Heaston**  
Air Pollution Control Officer

## **CONDITIONS:**

1. The toll-free telephone number that must be posted is 1-800-635-4617.
  
2. The owner/operator (o/o) shall maintain a log of all inspections, repairs, and maintenance on equipment subject to Rule 461. Such logs or records shall be maintained at the facility for at least two (2) years and shall be available to the District upon request.
  
3. Any modifications or changes to the piping or control fittings of the vapor recovery system require prior approval from the District.
  
4. The vapor vent pipes are to be equipped with pressure relief valves.
  
5. The Phase II Vapor Recovery System shall be tested in accordance with the requirements of Executive Order (EO) VR-202-C, as stated herein. The owner or operator shall conduct and pass the following tests ANNUALLY using the latest adopted version of the following test procedures:
  - a. TP-201.3, Determination of 2-Inch WC Static Pressure Performance of Vapor Recovery Systems of Dispensing Facilities (March 17, 1999);
  - b. Exhibit 8, Required Items in Conducting TP-201.3;
  - c. Exhibit 4; Determination of Static Pressure Performance of the Healy Clean Air Separator;
  - d. Exhibit 5, Vapor to Liquid Volume Ratio;
  - e. Exhibit 7, Nozzle Bag Test Procedure; and
  - e. Exhibit 9, ISD Operational Test Procedure.

The District shall be notified a minimum of 10 days prior to performing the required tests with the final results submitted to the District within 30 days of completion of the tests.

The District shall receive passing test report no later than six (6) weeks prior to the expiration date of this permit.

6. The Enhanced Vapor Recovery (EVR) 2-Point Phase I System shall be tested in accordance with the requirements of EO VR-202-E, as stated herein. The owner or operator shall conduct and pass the following tests at least once every three years using the latest adopted version of the following test procedures (next set of EVR Phase I testing due in 2013):
  - a. Static Torque of Rotatable Phase I Adaptors per TP201.1B;
  - b. Depending on system configuration, either TP-201-1D, Leak Rate of Drop Tube Overfill Prevention, Device and Spill Container Drain Valve; or TP-201.1C, Leak Rate of Drop Tube/Drain Valve Assembly; and
  - c. P/V valves in accord with TP-201.1E.

Passing test report shall be received by the District no later than six (6) weeks prior to the expiration date of this permit in those years when testing is required.

7. The annual throughput of gasoline shall not exceed 5,500,000 gallons per year. Throughput Records shall be kept on site and available to District personnel upon request. Before this annual throughput can be increased the facility may be required to submit to the District a site specific Health Risk Assessment (HRA) in accord with a District approved plan. In addition a public notice and/or comment period may be required.

8. Enhanced Vapor Recovery (EVR) 2-Point Phase I Vapor Control Equipment to be maintained in Compliance with Executive Order (EO) VR-102-D.

9. Healy EVR Phase II with ISD Equipment to be maintained in Compliance with EO VR-202-E, Dispensers shall be Uni-Hose type.

### 10. PROCEDURES FOR RESPONDING TO GDF VR SYSTEM FAILURE ALARMS:

- A. Within two (2) hours of the first ISD warning alarm the facility attendant shall notify the responsible company official or their designee and request service as soon as possible to correct the problem. All information relating to the alarm event and reporting shall be

promptly recorded and shall be made available to the Executive Officer/Air Pollution Control Officer upon request.

B. If the second ISD alarm sounds indicating this same problem still exists and gasoline dispensing is terminated, the ISD system may be reset to allow gasoline dispensing to resume only if:

(a) The gasoline dispenser(s) associated with the defective equipment is isolated and not operated until the required repairs are completed and all information associated with the repairs is recorded or,

(b) The station owner/operator and certified technician has made the required repairs and all information associated with the repairs is recorded or

(c) An Order of Abatement has been issued by the Hearing Board of the affected local air district allowing gasoline dispensing to continue or,

(d) There is written notification by a certified repair technician that additional time is needed to make the repairs because of the unavailability of a certified repair technician or unavailability of required parts and the service was requested within two (2) hours of the first ISD alarm, the repairs shall be made as soon as is reasonably possible thereafter and the ISD system may be reset to allow gasoline dispensing to resume for a maximum of three (3) additional days from when the ISD system was first reset. This written notification shall be kept with the ISD system records at the GDF and shall be made available to the Executive Officer/Air Pollution Control Officer upon request. In such case, the responsible company official or their designee shall also notify the affected local air district within twenty-four (24) hours of such written notification. The ISD system may only be reset one (1) time in this manner.