



MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

INACTIVE

B000898

Inactive type Permit has no description information.

EXPIRES LAST DAY OF: APRIL 2006

OWNER OF OPERATOR (Co.#2855)

West Coast Aggregate Supply, Inc.
119278 North Cadiz Road
Twentynine Palms, CA 92277

EQUIPMENT LOCATION (Fac.#408)

West Coast Aggregate Supply Inc. DBA Brubaker Mann
36011 Soap Mine Road
Barstow, CA 92311

Description:

ROCK PROCESSING SYSTEM consisting of:

EQUIPMENT

Capacity	Equipment Description
50	Primary jaw crusher
40	Secondary jaw crusher
250	Roll crusher
10	Screen, upper primary
7.5	Screen, lower primary
7.5	Screen, secondary
25	Conveyors, five @ 5 hp ea
3	Conveyors, two @ 1.5 hp ea
6	Conveyors, two @ 3 hp
18	Conveyors, six @ 3 hp
0	Dust control - water spray

CONDITIONS:

1. Materials processed shall contain sufficient natural and/or added moisture to ensure compliance with District Rules 401, 402 and 403.

Fee Schedule: 1 (c)

Rating: 417 bhp

SIC: 1442

SCC: 99999999

Location/UTM(Km): 501E/3862N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

West Coast Aggregate Supply, Inc.
P.O. Box 790
Thermal, CA 92274-0790

By: **COPY**
Brad Poiriez
Air Pollution Control Officer

2.The dust collector (District permit C002061) shall operate concurrently with the crushers and screens.

3.The material processed shall not exceed 125 tons per hour.

4.The owner/operator shall maintain a daily log of total material processed; weight, actual or estimated, of each product, by size. The log shall be maintained on site for two years and provided to District personnel on request.