



MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

INACTIVE

C008897

Inactive type Permit has no description information.

EXPIRES LAST DAY OF: APRIL 2005

OWNER OF OPERATOR (Co.#427)

Molded Fiber Glass Companies West
9400 Holly Road
Adelanto, CA 92301

EQUIPMENT LOCATION (Fac.#1095)

Molded Fiber Glass - Holly Rd
9400 Holly Road
Adelanto, CA 92301

Description:

DUST COLLECTOR UNIT A consisting of: Eurovac Central Dust Collection System, ducted vacuum lines, powered by a 50 hp fan motor, producing 1540 CFM at 7" hg pressure, Cyclonic Preseparator, 42" Secondary Cyclonic Separator, (6) 9" X 36 " Secondary Cartridge Filters, totaling 420 square foot of filter polyester fabric media area with a 5:1 air to cloth ratio. Control efficiency is 99.97% for 1 micron partical size.

CONDITIONS:

1. The owner/operator (o/o) shall maintain this dust collector in strict accord with those recommendations of the manufacturer/supplier and/or sound engineering principles which produce the minimum emissions of air contaminants.
2. This dust collector shall operate concurrently with trimming and sanding operations.
3. The o/o shall conduct a minimum program of inspection and maintenance on this equipment. The o/o shall maintain current and on-site for five (5) years a log of the following information, which shall be provided to District personnel upon request:
 - a. Weekly dust collector stack observation date and result (using USEPA Method 22, and USEPA Method 9 if necessary);
 - b. Quarterly cartridge and cartridge suspension system inspection date and results;
 - c. Date of cartridge replacements; and,
 - d. Date and nature of any system repairs.
4. This dust collector shall not discharge into the atmosphere an exhaust stream that exhibits greater than twenty percent opacity.

Fee Schedule: 7 (h)

Rating: 1 device

SIC: 3088

SCC: 30800720

Location/UTM(Km):
459E/2836N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

Molded Fiber Glass Companies West
9400 Holly Road
Adelanto, CA 92301

By: **COPY**
Eldon Heaston
Air Pollution Control Officer

5. This dust collector shall discharge no more than 1.02 pounds per hour of PM10 at a maximum concentration of 0.005 grains/dscf at the operating conditions given in the above description (BACT). This equipment does not require a regularly scheduled emission compliance test. However, emission compliance testing may be required at the discretion of the District.

6. The o/o shall maintain on-site a minimum inventory of replacement cartridges that assures compliance with these conditions.