



MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

PERMIT TO OPERATE

B000617

Operation under this permit must be conducted in compliance with all information included with the initial application, initial permit condition, and conditions contained herein. The equipment must be maintained and kept in good operating condition at all times. This Permit to Operate or copy must be posted on or within 8 meters of equipment. If a copy is posted, the original must be maintained on site, available for inspection at all times.

EXPIRES LAST DAY OF: DECEMBER 2026

OWNER OF OPERATOR (Co.#629)

Specialty Minerals, Inc
6565 Meridian Road
Lucerne Valley, CA 92356

EQUIPMENT LOCATION (Fac.#262)

Specialty Minerals, Inc
6565 Meridian Road
Lucerne Valley, CA 92356

Description:

TRUCK LOADOUT SYSTEM (GRANULES PLANT ROOF ROCK) consisting of: 166 HU Feeder from storage bin 181 TY to CBE 33, 4 hp CBE 33 Roof Rock Belt Conveyor to Truck Loadouts, Nos. 1, 2, and 3, at 1.5 hp

CONDITIONS:

1. Materials processed shall contain sufficient natural and/or added moisture to ensure compliance with District rules 401, 402 and 403. Sufficient water and the equipment to properly wet the materials being processed shall be maintained in operable condition on-site. [District Rule 1302(B)(1)(a)]
2. This unit shall operate concurrently with and vented to properly operating baghouse (DCL 15) under valid District permit C000635. [District Rule 1302(B)(1)(a)]

Fee Schedule: 1 (a)

Rating: 5.5 bhp

SIC: 1422

SCC: 30510105

Location/UTM(Km):
508E/3803N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

Specialty Minerals, Inc
P.O. Box 558
Lucerne Valley, CA 92356

By: **COPY**
Brad Poiriez
Executive Director