



MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

RENEWAL

B001675

Renewal type Permit has no description information.

EXPIRES LAST DAY OF: JUNE 2025

OWNER OF OPERATOR (Co.#1)

CEMEX Construction Materials Pacific LLC
16888 North E Street
Victorville, CA 92392

EQUIPMENT LOCATION (Fac.#5)

CEMEX - Black Mountain Quarry Plant
25220 Black Mountain Quarry Road
Apple Valley, CA 92307

Description:

CLINKER TRANSFER SYSTEM (STORAGE DOME) consisting of:

EQUIPMENT

Capacity	Equipment Description
0	Pan Conveyor - HPC1
0	Pan Conveyor - HPC2
0	Pan Conveyor - HPC3
150	Estimated horsepower

CONDITIONS:

1. The owner/operator (o/o) shall operate and maintain this equipment in strict accord with recommendations of the manufacturer and/or sound engineering practices.

1. The owner/operator (o/o) shall maintain this equipment in strict accord with those recommendations of the manufacturer/supplier and/or sound engineering principles which produce the minimum emissions of air contaminants.
[District Rule 204]

Fee Schedule: 1 (b)

Rating: 150bhp

SIC: 3241

SCC: 30500699

Location/UTM(Km): 476E/3826N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

CEMEX Construction Materials Pacific
LLC
16888 North E Street
Victorville, CA 92392

By: **COPY**
Brad Poiriez
Air Pollution Control Officer

2.This equipment shall not be operated without being vented to the baghouses with District Permits C001297 (HBH1A), C001303 (HBH1B) and C008824 (HBH1C).

2.This equipment shall not be operated without being vented to the baghouses with District permits C001297 (HBH1A), C001303 (HBH1B) and C008824 (HBH1C).
[District Rule 204]

3.The o/o shall conduct a minimum program of inspection and maintenance on this equipment. The o/o shall maintain current and on-site for five (5) years a log of the following information, which shall be provided to District personnel upon request:
a. Monthly (or as otherwise allowed by 40 CFR 63.1350) one minute observation date and result (using USEPA Method 22, and USEPA Method 9 if necessary); and,
b. Date and nature of any equipment/enclosure repairs.

3.The o/o shall conduct a minimum program of inspection and maintenance on this equipment. The o/o shall maintain current and on-site for five (5) years a log of the following information, which shall be provided to District personnel upon request:
a. Monthly (or as otherwise allowed by 40 CFR 63.1350) one-minute observation date and result (using USEPA Method 22, and USEPA Method 9 if necessary); and,
b. Date and nature of any equipment/enclosure repairs.
[District Rules 204 and 1203]

4.This equipment shall be operated in compliance with 40 CFR 63 Subpart LLL - National Emission Standards for Hazardous Air Pollutants from the Portland Cement Manufacturing Industry.

4.This equipment shall be operated in compliance with 40 CFR 63 Subpart LLL - National Emission Standards for Hazardous Air Pollutants from the Portland Cement Manufacturing Industry.
[District Rule 204; 40 CFR 63.1343]

5.This equipment shall not discharge into the atmosphere an exhaust stream that exhibits greater than ten percent opacity (40 CFR 63.1348).

5.This equipment shall not discharge into the atmosphere an exhaust stream that exhibits greater than ten percent opacity.
[District Rule 204; 40 CFR 63.1348]

6.A facility wide Comprehensive Emission Inventory (CEI) for all emitted criteria and toxic air pollutants must be submitted to the District, in a format approved by the District, upon District request.
[District Rule 107(b); H&S Code 39607 & 44341-44342; 40 CFR 51, Subpart A]