

MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park AvenueVictorville, CA92392-2310 760.245.1661 -- 800.635.4617 -- FAX760.245.2022

PERMIT TO OPERATE

C009762

Operation under this permit must be conducted in compliance with all information included with the initial application, initial permit condition, and conditions contained herein. The equipment must be maintained and kept in good operating condition at all times. This Permit to Operate or copy must be posted on or within 8 meters of equipment. If a copy is posted, the original must be maintained on site, available for inspection at all times.

EXPIRES LAST DAY OF: DECEMBER 2025

OWNER OF OPERATOR (Co.#629)

Specialty Minerals, Inc 6565 Meridian Road Lucerne Valley,CA92356

EQUIPMENT LOCATION (Fac.#262)

Specialty Minerals, Inc 6565 Meridian Road Lucerne Valley,CA92356

Description:

BAGHOUSE - DCL53 (GLASS SAND RAILROAD LOADOUT) consisting of:A Pebco Model IDC-260 dust collector with a total filter area of 260 sq.ft. The design airflow is 1200 acfm. This baghouse serves the Glass Sand Truck and Railroad Loadout.

CONDITIONS:

1.The owner/operator (o/o) shall maintain this baghouse in strict accord with those recommendations of the manufacturer/supplier and/or sound engineering principles which produce the minimum emissions of air contaminants.

[District Rule 1302(B)(1)(a)]

2. This baghouse shall operate concurrently with the Glass Sand Truck and Railroad Loadout operating under District Permit B000662, as applicable.

[District Rule 1302(B)(1)(a)]

Fee Schedule:7 (h)

Rating:1device

SIC:1422

SCC:30502006

Location/UTM(Km):508E/3803N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

Specialty Minerals, Inc P.O. Box 558 Lucerne Valley, CA92356

y: COPY

Brad Poiriez

Air Pollution Control Officer

- 3. The o/o shall conduct a minimum program of inspection and maintenance on this equipment. The o/o shall maintain current and onsite for five (5) years a log of the following information, which shall be provided to District personnel upon request:
- a. Weekly baghouse stack observation date and result (using USEPA Method 22, and USEPA Method 9 if necessary);
- b. Quarterly bag and bag suspension system inspection date and results;
- c. Quarterly reading of baghouse pressure drop, date and value (if a manometer is present);
- d. Date of bag replacements; and,
- e. Date and nature of any system repairs.

[District Rules 401; 40 CFR 60.672(a)]

- 4. This equipment shall be operated in compliance with applicable requirements of 40 CFR 60 Subpart OOO Standards of Performance for Nonmetallic Mineral Processing Plants.
- 5. This baghouse shall not discharge into the atmosphere an exhaust stream that exhibits greater than seven percent opacity. [40 CFR 60.672(a)(2)]
- 6. This baghouse shall discharge no more than 0.10 pounds per hour of PM10 at a maximum concentration of 0.01 grains/dscf at the operating conditions given in the above description (BACT). This equipment does not require a regularly scheduled emission compliance test. However, emission compliance testing may be required at the discretion of the District.

 [District Rule 404: more stringent grain loading is BACT based (1303(A)]
- 7.The o/o shall maintain on-site a minimum inventory of replacement bags that assures compliance with these conditions. [District Rule 1302(B)(1)(a)]
- 8.A facility wide Comprehensive Emission Inventory (CEI) for all emitted criteria and toxic air pollutants must be submitted to the District, in a format approved by the District, upon District request.

 [District Rule 107(b), H&S Code 39607 & 44341-44342, and 40 CFR 51, Subpart A]

Page 2 of 2 Permit: C009762 Issue Date: 01/24/2025