



MOJAVE DESERT AIR QUALITY MANAGEMENT DISTRICT

14306 Park Avenue Victorville, CA 92392-2310
760.245.1661 -- 800.635.4617 -- FAX 760.245.2022

PERMIT TO OPERATE

T002320

Operation under this permit must be conducted in compliance with all information included with the initial application, initial permit condition, and conditions contained herein. The equipment must be maintained and kept in good operating condition at all times. This Permit to Operate or copy must be posted on or within 8 meters of equipment. If a copy is posted, the original must be maintained on site, available for inspection at all times.

EXPIRES LAST DAY OF: DECEMBER 2026

OWNER OF OPERATOR (Co.#629)

Specialty Minerals, Inc
6565 Meridian Road
Lucerne Valley, CA 92356

EQUIPMENT LOCATION (Fac.#262)

Specialty Minerals, Inc
6565 Meridian Road
Lucerne Valley, CA 92356

Description:

SILO - BLENDER STORAGE BINS consisting of:

EQUIPMENT

Capacity	Equipment Description
9.72	Storage Silo W1 (13,000 cuft, 97,200 gallons)
8.83	Storage Silo W2 (11,810 cuft, 88,300 gallons) controlled by DCL 91 (C003714)
9.68	Storage Silo W3 (12,940 cuft, 86,800 gallons) controlled by DCL 94 (C007770)
7.71	Storage Silo W4 (10,304 cuft, 77,100 gallons) controlled by DCL 09 (C002334)
8.83	Storage Silo E1 (11,810 cuft, 88,300 gallons) controlled by DCL 92 (C003713)
8.75	Storage Silo E2 (11,700 cuft, 87,500 gallons) controlled by DCL 94 (C007770)
1.65	Storage Silo M1 (2000 cuft, 16,500 gallons)
7.71	Storage Silo E3 (10,304 cuft, 77,100 gallons) controlled by DCL 61 (C002332)

CONDITIONS:

Fee Schedule: 5 (c)

Rating: 628800 gallons

SIC: 1422

SCC: 30510205

Location/UTM(Km):
508E/3803N

This permit does not authorize the emission of air contaminants in excess of those allowed by law, including Division 26 of the Health and Safety Code of the State of California and the Rules and Regulations of the District. This permit cannot be construed as permission to violate existing laws, ordinances, statutes or regulations of this or other governmental agencies. This permit must be renewed by the expiration date above. If billing for renewal fee required by Rule 301(c) is not received by expiration date above, please contact the District.

Specialty Minerals, Inc
P.O. Box 558
Lucerne Valley, CA 92356

By: **COPY**
Brad Poiriez
Executive Director

1. The silos above which have a dust collector (designated by a DCL number) shall only operate concurrently with its respective DCL. The remainder of the silos contain materials of a sufficiently large particle size to not warrant dust collection at the present time.

2. A facility wide Comprehensive Emission Inventory (CEI) for all emitted criteria and toxic air pollutants must be submitted to the District, in a format approved by the District, upon District request.

[District Rule 107(b), H&S Code 39607 & 44341-44342, and 40 CFR 51, Subpart A]